Office of Health Care Assurance

State Licensing Section

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

Facility's Name: Sharolyn L Galamay LLC (ARCH)	CHAPTER 100.1
Address: 91-1141 Kauiki Street, Ewa Beach, Hawaii, 96706	Inspection Date: March 8, 2019 Annual

THIS PAGE MUST BE SUBMITTED WITH YOUR PLAN OF CORRECTION. IF IT IS NOT, YOUR PLAN OF CORRECTION WILL BE RETURNED TO YOU, UNREVIEWED.

YOUR PLAN OF CORRECTION MUST BE SUBMITTED WITHIN TEN (10) WORKING DAYS. IF IT IS NOT RECEIVED WITHIN TEN (10) WORKING DAYS, YOUR STATEMENT OF DEFICIENCIES WILL BE POSTED ONLINE, WITHOUT YOUR RESPONSE.

\$11-100.1-23 Physical environment. (r) Facilities shall be maintained in accordance with provisions of state and local zoning, building, fire safety and health codes. FINDINGS Smoke detector in Bedroom #1 for family use located next to Resident Bedroom #2 was chirping. PART 1 DID YOU CORRECT THE DEFICIENCY? USE THIS SPACE TO TELL US HOW YOU CORRECTED THE DEFICIENCY	RULES (CRITERIA)	PLAN OF CORRECTION	Completion Date
	Facilities shall be maintained in accordance with provisions of state and local zoning, building, fire safety and health codes. FINDINGS Smoke detector in Bedroom #1 for family use located next	DID YOU CORRECT THE DEFICIENCY? USE THIS SPACE TO TELL US HOW YOU	Date

RULES (CRITERIA)	PLAN OF CORRECTION	Completion Date
§11-100.1-23 Physical environment. (r) Facilities shall be maintained in accordance with provisions of state and local zoning, building, fire safety and health codes. FINDINGS Smoke detector in Bedroom #1 for family use located next to Resident Bedroom #2 was chirping.	PART 2 FUTURE PLAN USE THIS SPACE TO EXPLAIN YOUR FUTURE PLAN: WHAT WILL YOU DO TO ENSURE THAT IT DOESN'T HAPPEN AGAIN?	Date

Licensee's/Administrator's Signature: _	
Print Name:	
Date:	